
LA-UR-03-3903
June 2003

Los Alamos National Laboratory Technical Area 16 Part B Permit Renewal Application

Revision 4.0

Prepared by:

*Los Alamos National Laboratory
Risk Reduction and Environmental Stewardship Division
Solid Waste Regulatory Compliance Group (RRES-SWRC)
Los Alamos, New Mexico 87545*

**Los Alamos National Laboratory
Technical Area 16
Part B Permit Renewal Application**

Revision 4.0

**LA-UR-03-3903
June 2003**

Prepared by:
Los Alamos National Laboratory
Risk Reduction and Environmental Stewardship Division
Solid Waste Regulatory Compliance Group (RRES-SWRC)
Los Alamos, New Mexico 87545

TABLE OF CONTENTS

LIST OF TABLES.....	ii
LIST OF ATTACHMENTS.....	iii
LIST OF SUPPLEMENTS.....	iv
LIST OF ABBREVIATIONS/ACRONYMS.....	v
1.0 INTRODUCTION	1-1
2.0 TREATMENT AT TECHNICAL AREA 16	2-1
2.1 TA-16 OPEN BURNING UNITS	2-1
2.2 AUTHORIZED WASTE IDENTIFICATION	2-2
2.3 CONTAINMENT SYSTEMS	2-2
2.4 INSPECTION SCHEDULES AND PROCEDURES.....	2-3
2.5 SPECIAL REQUIREMENTS FOR IGNITABLE, REACTIVE, AND INCOMPATIBLE WASTES.....	2-3
2.6 CLOSURE	2-3
2.7 CONTROL OF RUN-ON AND RUNOFF	2-3
3.0 OTHER FEDERAL LAWS.....	3-1
4.0 CORRECTIVE ACTION FOR SOLID WASTE MANAGEMENT UNITS	4-1
5.0 CERTIFICATION	5-1
6.0 REFERENCES	6-1

LIST OF TABLES

<u>TABLE NO.</u>	<u>TITLE</u>
1-1	Regulatory References and Corresponding Permit Renewal Application Location
4-1	Technical Area (TA) 16 Solid Waste Management Units (SWMU) at or in the Vicinity of the TA-16 Burn Ground

LIST OF ATTACHMENTS

<u>ATTACHMENT</u>	<u>TITLE</u>
A	Facility Description
B	Waste Analysis Plan
C	Inspection Plan
D	Personnel Training Plan
E	Contingency Plan
F	Closure Plan for the Technical Area 16 Open Burning Units
G	Technical Area (TA) 16 Open Burning Units Management
H	Environmental Performance Standards

LIST OF SUPPLEMENTS

SUPPLEMENT

TITLE

4-1

Solid Waste Management Units in the Immediate Vicinity of the Technical Area 16 Burn Ground: Information Extracted from "The 2003 Solid Waste Management Unit Report"—LA-UR-03-6000

LIST OF ABBREVIATIONS/ACRONYMS

20.4.1 NMAC	New Mexico Administrative Code, Title 20, Chapter 4, Part 1
EPA	U.S. Environmental Protection Agency
HE	high explosives
HRMB	Hazardous and Radioactive Materials Bureau
LANL	Los Alamos National Laboratory
MDA	Material Disposal Area
NMED	New Mexico Environment Department
OB	open burning
SWMU	solid waste management unit
SWPP	Stormwater Pollution Prevention
TA	technical area